ISTA/P

Programmings parallel MOST

*fixed sorting according to execution sequence

Encodings

*fixed sorting according to execution sequence

| Control module | Action | Result / fault code | Status | Type | Hardwi index | are Part number prog. ECU oli | |
|----------------|--------|------------------------|----------|------|-----------------|----------------------------------|---------|
| ULF-SBX | Code C | Successful | V | Sys | 07 | 9187625 | 9229740 |
| во | Code C | Successful | 4 | Sys | 50 | 9178853 | 9223675 |

Additional actions

| Control | module Action | Result / fault code | Status |
|---------|--------------------------|---------------------|----------|
| - | Update integration level | Successful | V |
| - | Vehicle order alignment | Successful | * |

The following control modules have not responded or responded incorrectly

| Control module | Result / fault code | Status. |
|----------------|---|----------|
| ULF-SBX | The programming status is 12. The control module could not be identified. | <u> </u> |
| во | The programming status is 5. The control module could not be identified. | Δ |

Date: 5/6/2010 VIN:VF94206

ISTA/P

Final report

Session name:

E88_VE94206

Duration:

00:11:57

Measures plan implementation successful:

Cancellation by user

Concluding work, notes:

Not fitted

Change vehicle order:

No

Header data

| Date: | 5/6/2010 | Time: 10:08:40 AM | ISTA/P version; 37.2.0.4 | |
|--------------------------------|--|------------------------------|----------------------------------|--|
| Model series: | E88 | Type/description: | - / E88 Conv N54B30U0 LHD US | |
| Mileage: | | Veh | cle ID number: WBAUN93538VE94206 | |
| Integration level | (plant): | Integration level (old): | Integration level (new): | |
| | | | | |
| E89X-08-03-520 | | E89X-10-03-504 | E89X-10-03-504 | |
| E89X-08-03-520 Time criterion: | | E89X-10-03-504 Paint code: - | E89X-10-03-504 Upholstery code: | |
| | distriction of the control of the co | | | |

SA numbers:

Date: 5/6/2010 VIN:VF94206

ISTA/P

Final report

Session name:

E88_VE94206

Duration:

00:48:04

Measures plan implementation successful:

Yes

Concluding work, notes:

Not fitted

Change vehicle order:

No

Header data

Time: 11:53:08 AM Date:

Model series:

E88

Type/description:

UN93 / E88 Conv N54B30U0 LHD US

Mileage:

Integration level (plant):

Integration level (old):

Integration level (new):

E89X-08-03-520

E89X-10-03-504

E89X-10-03-504

Time criterion: Upholstery code:

E words:

B090

K words:

SA numbers:

1CA, 249, 255, 2CH, 2VB, 319, 321, 346, 3AP, 430, 431, 441, 459, 473, 488, 494, 4A3, 4NA, 4UT, 502, 521, 522, 524, 534, 540, 563, 570, 5GA, 639, 645, 663, 676, 693, 694, 6FL,

704, 823, 845, 850, 853, 876, 925