



Official

Carly Diagnostics Report

1 Coupe (E82), Build Year 2011

categorized as Compact class was diagnosed with Carly on

Apr 09 2019

Carly found 14 control units.

8 fault codes were detected.



Motor Control

Engine / Motor	
Fault Code: 002DE5	X
Fault Explanation: Tank level sensor, right: signal	
Fault Code: 002DE4	
Fault Explanation: Tank level sensor, left: signal	



ABS / DSC / Brake

Dynamische Stabiliteits Kontrolle / DSC


Fault Code: 005DA3

Fault Explanation: :Speed sensor front right detecting starting v comparison. / Yaw rate sensor DRS sends signal DrsPSIP2 = Init Failed status. (DRS-type MM 3.x). / Drivers outlet valve (dump) shorted front right / Yaw rate sensor: DRS sends signal DrsPSIP2 = INIT state error (DRS-type MM 3.x). / Yaw rate sensor: DRS sends signal DrsPSIP2 = Init state error;. DRS-type MM 3.x --- (DSC: DSC sensor internal) / Speed sensor, rear detecting starting v comparison / Wheel speed sensor, front right start detection (comparison)

Fault Code: 005DC6

Fault Explanation: :Valve HSV1: Error cyclic valve and relay test. / Valve (HSV1): Error cyclic valve and relay test. / Valve HSV1: Error cyclic relay valve and test --- (DSC: control valve actuation device) / Rotation detection right rear.

X



Instrumentation

Instrument cluster / Kombiinstrument

Fault Code: 009319

Fault Explanation: :Error signal tank level raw data links / Error signal Raw data container filling level Left / LEVER SENSOR RIGHT / Stoplight open load or short circuit to Ubat / HEBELGEBER1 / CAN signal invalid speed wheel Motorcycle H / Signal time second counter relative motorcycle invalid

Fault Code: 00A554

Fault Explanation: :ALIVE error Phone / live phone

X

Central info display / Zentrales Display

ECU OK, no Fault Code



Heating / AC

Air conditioning / Klimaanlage

ECU OK, no Fault Code



Immobilizer System

CAS

Fault Code: 00A0B5

Fault Explanation: :Signal detection speed error / DFAHL cable break A0B5



Audio / Navigation / Communication

Car Communication Computer CCC

ECU OK, no Fault Code



Car Communication Computer CCC

Fault Code: 00E1CD

Fault Explanation: :Awakening device has three times unsuccessfully, the network tries to awaken (Error WakeUp Failed) / Total ring could not be started (Error WakeUp Failed).





Seats

Seats / Sitze ECU OK, no Fault Code	✓
Seats / Sitze ECU OK, no Fault Code	✓



Systems

Fuel pump / Kraftstoffpumpe ECU OK, no Fault Code	✓
Tire pressure control / Reifendruck Kontrolle ECU OK, no Fault Code	✓
Car Communication ECU OK, no Fault Code	✓



Other

ECU 92 ECU OK, no Fault Code	✓
--	---